



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

August 14, 2006

Supervisor

[Signature]

Mine Name: Briggs Quarry

Operator Name: K Four Ranch, Inc. (Barry Peterson)

Permit number: M0030058

Inspection Date: August 8, 2006

Time: 1:00 pm

Inspector(s): Lynn Kunzler, DOGM

Other Participants: None

Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

1. This site was inactive at the time of this inspection. It appears that there has been no activity so far during this season. The Disturbed area remains the same at about 4.8 acres. There were no safety or erosion problems noted.

Conclusions and Recommendations:

- 1 This operation is in compliance at this time. However, with Mr. Peterson purchasing the neighboring Sierra Starlight Quarry (M0030049), A Large Mining Notice will need to be submitted and approved.

Continue to monitor the site when in the area.

Photos were taken to document site conditions.

Inspector's Signature

[Signature]

Date: August 14, 2006

LK:pb

O:\M003-BoxElder\S0030058-Briggsquarry\inspections\insp-08082006.doc